


ASSEMBLY INSTRUCTIONS / 1500 SERIES COMPUTER TABLE

1. Place the table top upside down on a clean, smooth, surface. Assemble the frame and legs together.
 Position the wire management tray at the rear next to the two grommet holes. Place the 90 degree flange of the wire management tray under the leg bracket and next to the table top. Push leg brackets into rails until all holes on legs and rails are aligned. Attach to the table top with (20) #10 x 3/4" Phillips head screws into the predrilled holes in the top. **Do not tighten any screws until all screws have been partially started.** Be careful not to strip the wood by over tightening.
2. Install the glides into the bottom of the fixed height leg or assemble the adjustable leg stems to the main leg by setting at the desired table height and securing in place with the machine screws provided.
3. Place the table into position in the room and level the unit to the floor using the adjustable glides. Adjust glides as needed for all four legs to contact the floor firmly. Install the plastic grommets into the cutouts in the work surface.



Two persons required for assembly